

Inspection Photos

2/5/2024

Operator: CAERUS PICEANCE LLC #10456

Location ID: 335793

Inspection Doc: 696205596

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 1: Photos 1-2 taken from the east end of the Location. Photos provide an overview of the Location from south, southwest, northwest to north.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 3: Photo example showing the WPS lacks stabilization; BMPs to stabilize the WPS, as well as to minimize erosion, degradation and sediment transport missing or insufficient; tracking/rutting observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 4: Photo example showing the WPS lacks stabilization; BMPs to stabilize the WPS, as well as to minimize erosion, degradation and sediment transport missing or insufficient; tracking/rutting observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 5: Photo example showing the access road lacks stabilization; BMPs to stabilize, as well as to minimize erosion, degradation and sediment transport missing or insufficient; tracking/rutting observed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



February 5, 2024

Photo 6: Photos taken from the northeast end of the WPS. Photo shows the berm along the perimeter of the pad is no longer in proper functioning condition; stormwater runoff from the pad has resulted in erosion, degradation and off-site sediment transport.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 7: Continue from photo 6. Photos examples showing erosion/degradation due to stormwater runoff from the WPS.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 8: Photos taken from the south end of the Location. Photo shows halogeton established on the Location.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 335793



Photo 9: Lines at tanks lack cap/plug.