

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM CREEK RANCH 29-4 (D29E) Pad

Location #: 334827



Photo # 6102 From entrance to location




Photo # 6103 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM CREEK RANCH 29-4 (D29E) Pad

Location #: 334827



Photo # 6104 Location



Photo # 6105 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MAMM CREEK RANCH 29-4 (D29E) Pad

Location #: 334827



Photo # 6106 Location



Photo # 6107 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife