

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2024

Submitted Date:

02/11/2024

Document Number:

696305945**FIELD INSPECTION FORM**Loc ID 431817 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
431816	WELL	TA	09/22/2023	OW	123-36799	Shable Federal LB33-78HN	TA
431818	WELL	TA	09/22/2023	OW	123-36800	Shable LB 32-68HN	TA

**General Comment:**[Follow-Up Inspection to FIR 696305007 dated 06.12.2023](#)

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Black Container at 33-78HN Wellsite is missing Lable, see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	03/11/2024
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	STORAGE OF SUPL		
Comment:	Unused Secondary Containment and Stand at 32-68HN Wellsite; see photos		
Corrective Action:	Comply with Rule 606	Date:	03/11/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 2		corrective date
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	

Type: VRU	# 2		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 5		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 3		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	TA Wellhead - Shut-In for HZ Prep		
Corrective Action:			Date:
Type: Pump Jack	# 2		
Comment:	Hydraulic Units		
Corrective Action:			Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 431816

Type: WELL

API Number: 123-36799

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: TA - Since 09.22.2023. MIT 04.21.2023

Corrective Action:

Date:

Facility ID: 431818

Type: WELL

API Number: 123-36800

Status: TA

Insp. Status: TA

Idle Well

Purpose: ☐ Shut In

☒ Temporarily Abandoned

Reminder:

Comment: TA - Since 09.22.2023. MIT 03.30.2023

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Routine Field Inspection. Unused Secondary Containment at 32-68HN Wellsite	petrie	02/11/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696305946	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6425686">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6425686</a>