

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/33NENE

Location ID: 335435

Date: 2/12/2024



Location Entrance – Photo #09201



Wellheads – Photo #09202

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/33NENE

Location ID: 335435

Date: 2/12/2024



Wellheads – Photo #09204



Separators – Photo #09208

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/33NENE

Location ID: 335435

Date: 2/12/2024



Tank Battery – Photo #09209



Lack of Stabilization – Photo #09206

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/33NENE

Location ID: 335435

Date: 2/12/2024



Lack of Stabilization – Photo #09211

Lack of Stabilization – Photo #09212

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/33NENE

Location ID: 335435

Date: 2/12/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09214**



Lease Road Lacks Stabilization – Photo #09213