

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146



Photo # 6307 From entrance to location




Photo # 6308 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146



Photo # 6309 Location



Photo # 6310 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146



Photo # 6311 Location



Photo # 6312 Wellhead sign weathered & peeling

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 44-18 pad

Location ID: 335146



Photo # 6313 Wellhead sign weathered & peeling



Photo # 6314 Open ended load line