

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/30/2024

Submitted Date:

02/08/2024

Document Number:

701008075**FIELD INSPECTION FORM**Loc ID 321546 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 61650Name of Operator: MURFIN DRILLING COMPANY INCAddress: 250 N WATER ST STE 300City: WICHITA State: KS Zip: 67202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Goodrich, Cristina	(316) 858-8664	cgoodrich@murfininc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207096	WELL	TA	05/01/2022	OW	017-06031	UPRR 1-1	PA

General Comment:[P&A Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Dirt road through farm ground and CRP		
Corrective Action:		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Stickers on tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Lease sign at tank battery		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date: _____		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: FWKO	# 1		
Comment:	FWKO on the west side of tank battery		
Corrective Action:	Remove from location and begin final reclamation		Date: 03/07/2024
Type: Pump Jack	# 0		
Comment:	Removed from location		
Corrective Action:			Date:
Type: Prime Mover	# 0		
Comment:	Removed from location		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Electric panel and cathodic rectifier		
Corrective Action:	Remove from location and begin final reclamation		Date: 03/07/2024
Type: Deadman # & Marked	# 0		
Comment:	Removed from location		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	400 BBLS	STEEL AST		38.689220,-102.407860	
Comment:						
Corrective Action: Remove tanks from location and begin final reclamation					Date:	03/07/2024

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities											
Facility ID:	207096	Type:	WELL	API Number:	017-06031	Status:	TA	Insp. Status:	PA		
Cement											
Cement Contractor											
Contractor Name:					HP Oilfield Services					Contractor Phone:	
Surface Casing											
Cement Volume (sx):										Circulate to Surface:	
Cement Fall Back:										Top Job, 1" Volume:	
Intermediate Casing											
Cement Volume (sxs):										Good Return During Job:	
Production Casing											
Cement Volume (sx):										Good Return During Job:	
Plugging Operations											
Depth Plugs(feet range):					2287/1689/547					Cement Volume (sx):	155 SXS
Good Return During Job:					YES					Cement Type:	Class A 3% CaCl
Comment:					HALDE WATER, HP OILFIELD SERVICES, HURRICANE WELL SERVICE. MIRU HP, PUMP 15 SXS CMT W/3% CaCl @ 2287'. MIRU HURRICANE POOH W/TBG 1689'. WOC 1HR TAG @ 2150'. MIRU HP, PUMP 20 SXS CMT W/3% CaCl. MIRU HURRICANE, POOH W/TBG TO 1500'. WOC 1HR TAG @ 1520'. MIRU HP, PUMP 45 SXS CMT W/3% CaCl. MIRU HURRICANE, POOH W/TBG TO 547'. MIRU HP, PUMP 65 SXS W/CMT TO SFC. MIRU HURRICANE, POOH W/TBG. MIRU HP, PUMP 10 SXS CMT TO TOP OFF CSG.						
Corrective Action:										Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403681775	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6423484