

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-8D (H21) Pad

Location #: 335374



Photo # 6542 From entrance to location



Photo # 6543 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-8D (H21) Pad

Location #: 335374



Photo # 6544 Location



Photo # 6545 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-8D (H21) Pad

Location #: 335374



Feb 13, 2024 at 11:55:30 AM  
CO



Feb 13, 2024 at 12:01:44 PM  
CO

Photo # 6546 Location

Photo # 6547 Location

# Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-8D (H21) Pad

Location #: 335374



Photo # 6548 PRV vent line lacks cap



Photo # 6549 PRV vent line lacks cap

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-8D (H21) Pad

Location #: 335374



Photo # 6550 PRV & rupture disc vent lines lack caps




Photo # 6551 Rupture disc vent line lacks cap

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-8D (H21) Pad

Location #: 335374



Photo # 6552 Rupture disc vent line lacks cap




Photo # 6553 PRV vent line lacks cap

## Inspection Photos

Location Name: CAERUS PICEANCE LLC GMR 21-8D (H21) Pad

Location #: 335374



Photo # 6554 PRV vent line lacks cap

