

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 2/13/2024



Location Entrance – Photo #09272

Wellheads – Photo #09273

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 2/13/2024



Separators – Photo #09279



Tank Battery – Photo #09280

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 2/13/2024



Stored Equipment – Photo #09281



Open-Ended Line – Photo #09282

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 2/13/2024



Lack of Stabilization – Photo #09284

Lack of Stabilization – Photo #09285

Inspection Photos

Location Name: CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location ID: 335687

Date: 2/13/2024



**Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09287**

Lack of Stabilization on Lease Road – Photo #09286