

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/15/2024

Submitted Date:

02/18/2024

Document Number:

708903085**FIELD INSPECTION FORM**Loc ID 335307 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☒
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:31 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260285	WELL	PR	11/08/2013	GW	045-07841	COUEY 31-8 (B31)	PR
260286	WELL	PR	07/29/2002	GW	045-07842	COUEY 31-7 (B31)	PR
260287	WELL	PR	12/06/2002	GW	045-07843	COUEY 31-2 (B-31)	PR
260288	WELL	PR	08/06/2002	GW	045-07844	SHAEFFER 31-3 (B31)	PR
262207	WELL	PR	05/10/2012	GW	045-08003	COUEY 31-7B2 (B31)	PR
262208	WELL	PR	07/23/2002	GW	045-08004	COUEY 31-1C2 (B-31)	PR
262968	WELL	PR	08/09/2002	GW	045-08077	COUEY 30-15 (B31)	PR

General Comment:**CECMC Inspection Report Summary**

On 02/15/2024 at approximately 10:37 hours, I, Compliance Specialist, Wayne Smelser

Conducted a follow up inspection at CAERUS PICEANCE LLC B31 Pad

Location # 335307 in Garfield County Colorado.

Please refer to inspection 708902346 conducted on 11/22/2023, previous corrective action has not been completed.

Location is within High Priority/Density/Black Bear Habitat areas.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Housekeeping - Stained gravel in secondary containment with a CA date of 12/07/2023

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at intersection of public road & start of lease road		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911/970-285-2615	
Corrective Action:		Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained gravel inside secondary containment		
Corrective Action:	Remove and properly dispose of all stained soils and gravel.		Date: 12/07/2023

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Cattle panels		

Corrective Action:		Date:	
Equipment:		corrective date	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment: All wells on plunger lift			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment: Summit Midstream			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment: Liquid nitrogen tank			
Corrective Action:		Date:	
Type: Other	# 1		
Comment: Telemetry			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment: Pressure transducers located on all bradenhead, all bradenhead valves are accessible			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLS	STEEL AST		,
Comment: Centralized containment					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity) 500 gal	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Unlined containment				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	In containment with single 300 bbl condensate tank near entrance to location.				
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Unlined containment				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	HEATED STEEL AST		,
Comment:	In separate containment with 1000 gal methanol tank as you come onto location. Tank equipped with telemetry				
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Unlined containment				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLS	STEEL AST		,
Comment:	Centralized containment Tanks equipped with telemetry				
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			
Comment:	Unlined containment			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	260285	Type:	WELL	API Number: 045-07841	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	260286	Type:	WELL	API Number: 045-07842	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	260287	Type:	WELL	API Number: 045-07843	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	260288	Type:	WELL	API Number: 045-07844	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	262207	Type:	WELL	API Number: 045-08003	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	262208	Type:	WELL	API Number: 045-08004	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:
Facility ID:	262968	Type:	WELL	API Number: 045-08077	Status: PR	Insp. Status: PR
Producing Well						
Comment:	Producing, well on plunger lift					
Corrective Action:						Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						Sparse to none in some areas
		Compaction				
		Culverts				
		Ditches				
		Gravel				Sparse to none
Compaction						Light compaction in some areas

Comment: Some signs of lack of stabilization/compaction in small areas near both tank batteries.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Please refer to Housekeeping for observed compliance issue.	smelserw	02/18/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903087	Inspection 708903085 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6433875
708903088	Inspection 708903085 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6433876