

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/08/2024

Submitted Date:

02/11/2024

Document Number:

708903032**FIELD INSPECTION FORM**Loc ID 334660 Inspector Name: Smelser, Wayne On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

29 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283221	WELL	PR	06/15/2008	GW	045-11910	SHIDELER 25-8 (E30E)	PR
283222	WELL	PR	06/12/2008	GW	045-11909	SHIDELER 25-1C (E30E)	PR
283223	WELL	PR	05/26/2008	GW	045-11908	SHIDELER 25-8C (E30E)	PR
283224	WELL	PR	05/26/2008	GW	045-11905	SHIDELER 30-11B (E30E)	PR
283225	WELL	PR	06/02/2008	GW	045-11903	SHIDELER 30-2C (E30E)	PR
283226	WELL	PR	05/30/2008	GW	045-11902	SHIDELER 30-3C (E30E)	PR
283229	WELL	PR	06/06/2008	GW	045-11900	SHIDELER 30-6B (E30E)	PR

**General Comment:****CECMC Inspection Report Summary**

On 02/08/2024 at approximately 12:59 hours, I, Compliance Specialist, Wayne Smelser  
Conducted an on-site inspection at CAERUS PICEANCE LLC SHIDELER 25-8 (E30E) Pad.  
Location # 334660 in Garfield County Colorado.  
Location is within High Priority/Density/Black Bear Habitat areas.  
While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Tanks & Berms - Multiple holes in secondary containment liner/liner needs maintenance with a CA date of 03/02/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This is a summary of inspection report.

Split pad/Shared facilities with location # 334630

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the units indicates the storage tanks are full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tanks.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Sign at entrance to location		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		
In Containment:	No			
Comment:				
<input type="checkbox"/>	Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Bollards		
Corrective Action:		Date:	

Type	LOCATION		
Comment:	Barbed wire fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Horizontal Heated Separator	# 15		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Bear proof trash container		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Telemetry		
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Pressure transducers located on all bradenhead. All bradenhead valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 15		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	1000 GAL	STEEL AST		,	
Comment:	Centralized containment					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal						
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	500 BBLs	STEEL AST		,	
Comment:				<a href="#">Centralized containment</a> <a href="#">Tanks equipped with telemetry</a>		
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Inadequate	Walls Insufficient		Inadequate		
Comment:				<a href="#">Multiple holes in secondary containment liner/liner needs maintenance</a>		
Corrective Action:				<a href="#">The liner will be sufficiently impervious so that any discharge from a primary containment system will not escape containment before cleanup occurs.</a>		Date: <u>03/02/2024</u>
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	283221	Type:	WELL	API Number:	045-11910	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	283222	Type:	WELL	API Number:	045-11909	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	283223	Type:	WELL	API Number:	045-11908	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	283224	Type:	WELL	API Number:	045-11905	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	283225	Type:	WELL	API Number:	045-11903	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	283226	Type:	WELL	API Number:	045-11902	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			
Facility ID:	283229	Type:	WELL	API Number:	045-11900	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing, well on plunger lift								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		Chemical tank containment
		Ditches				
Compaction						Large amount of light compaction
		Culverts				
		Compaction				Light compaction
		Gravel				Sparse to none
Gravel						Sparse to none

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Limited Stormwater inspection in some areas due to snow.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Please refer to Tank & Berms for observed compliance issues.	smelserw	02/11/2024
Split pad/Shared facilities with location # 334630		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403684643	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6426863">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6426863</a>
708903034	Inspection 708903032 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6426860">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6426860</a>
708903035	Inspection 708903032 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6426861">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6426861</a>