

Inspection Photos
Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad
Location #: 334578



Photo # 6832 From entrance to location




Photo # 6833 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad
Location #: 334578



Photo # 6834 Location



Photo # 6835 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578



Photo # 6836 Location



Photo # 6837 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578




Photo # 6838 Emergency contact # incorrect



Photo # 6839 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578



Photo # 6840 Hole in liner/liner needs maintenance



Photo # 6841 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578



Photo # 6842 Hole in liner/liner needs maintenance



Photo # 6843 Holes in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578



Photo # 6844 Hole in liner/liner needs maintenance



Photo # 6845 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578



Photo # 6846 Hole in liner/liner needs maintenance



Photo # 6847 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578



Photo # 6848 Location

Photo # 6849 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC MILLER 11-7 (G11W) Pad

Location #: 334578



Photo # 6850 Hole in liner/liner needs maintenance



Photo # 6851 Hole in liner/liner needs maintenance