

**Inspection Photos**  
**Location Name: Federal Plover 28-5X**  
**Location ID: 331082**



Energy and Carbon Management Commission  
40.63536, -104.10208, 4840.7ft  
02/15/2024 13:28:48

**Photo 1 – Pumping Unit**



Energy and Carbon Management Commission  
40.63535, -104.10199, 4834.1ft  
02/15/2024 13:29:23

**Photo 2 – 24-Hour Emergency Contact Number from previous Operator is still present**

**Inspection Photos**  
**Location Name: Federal Plover 28-5X**  
**Location ID: 331082**



**Photo 3 – Wellhead**



**Photo 4 – Gas Engine**