

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335814

Date: 2/20/2024



Location Entrance – Photo #09368



Wellheads – Photo #09369

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335814

Date: 2/20/2024



Separators – Photo #09373



Tank Battery – Photo #09370

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335814

Date: 2/20/2024



Lack of Stabilization – Photo #09372



Lack of Stabilization – Photo #09374

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWNW

Location ID: 335814

Date: 2/20/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09375