

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2024

Submitted Date:

02/22/2024

Document Number:

698705815**FIELD INSPECTION FORM**Loc ID 410129 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 2001 16TH STREET SUITE 900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
/, Chevron		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections
Silver, Randy		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
302002	WELL	TA	05/14/2020	OW	123-30177	GREEN USX EE 13-11P	TA

General Comment:[Wellsite Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	DEBRIS		
Comment:	Debris need to be removed and hauled off		
Corrective Action:	Comply with rule 606	Date:	03/05/2024

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Bradenhead	# 1			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 1			
Comment:				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			
	Date:		

Flaring:			
Type			
Comment:			
Corrective Action:			
	Date:		

Inspected FacilitiesFacility ID: 302002 Type: WELL API Number: 123-30177 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA
6A on file
Flowline valves are closed & LOTO

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 09/23/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<u>ECMC Inspection Report Summary</u> <u>On Thursday February 22 2024 at approximately 9:50 am, I, Inspector Abe Serna,</u> <u>conducted an on-site inspection.</u> <u>Location: Green USX EE 13-11P</u> <u>Operator: Noble Energy</u> <u>API#: 123-30177</u> <u>County: Weld</u> <u>While there, I observed a SI Well</u> <u>During this inspection the following possible compliance issues were observed:</u> <u>Debris: Rule 606 Corrective Action Date of 3-5-24 see photos</u> <u>Weather conditions: Cloudy</u> <u>A follow up on this site inspection needs to be conducted to ensure the</u> <u>Compliance issues have been corrected to comply with ECMC rules.</u> <u>This is a summary of inspection report.</u> <u>Any corrective actions from previous inspections that have not been addressed are still</u> <u>applicable</u>	<u>sernaa</u>	<u>02/22/2024</u>

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
<u>698705816</u>	<u>Photo</u>	<u>http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6438623</u>