

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335566

Date: 2/20/2024



Location Entrance – Photo #09392



Location Entrance – Photo #09396

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335566

Date: 2/20/2024



Wellheads – Photo #09393



Separators – Photo #09397

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335566

Date: 2/20/2024



Tank Battery – Photo #09401



Lack of Stabilization – Photo #09394

Inspection Photos

Location Name: CAERUS PICEANCE LLC, CHEVRON-66S96W/4SWSW

Location ID: 335566

Date: 2/20/2024



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit
– Photo #09404