

Inspection Photos

Loc: 485654

Operator: BNL (ENTERPRISE) INC

Inspection Date: 2/21/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south toward the access road. The sides of the road will need to be reclaimed. The road is not crowned and there are no ditches for stormwater which may become a problem.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 2/21/2024

Inspection Photos



Photo 2. The drainage crossing has a large culvert but there is no outlet protection and loose gravel is falling into the culvert.



Photo 3. The embankment along the road side at the culvert is not stabilized and loose gravel is falling into the culvert.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 4. Facing northwest toward the access road. The side of the road needs to be seeded and stabilized and the road needs to be crowned and graveled.



Inspection Photos



Photo 5. Facing northwest toward the location..



Inspection Photos



Photo 6. Facing toward the drilled well. The drill cuttings are not properly stored with containment and have spread off the liner.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 2/21/2024

Inspection Photos



Photo 7. The containers are filled with drill cuttings and appear to be leaking out from the back gate. The drill cuttings are not properly stored with containment and have spread off the liner.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 2/21/2024

Inspection Photos



Photo 8. Facing toward the soil stock pile. The stock pile will need to be seeded before the growing season unless it will be re-spread for reclamation before that time.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:485654 | Date: 2/21/2024

Inspection Photos



Photo 9. There are several area where the silt fence is not maintained..

