

Inspection Photos

API: 011-06032

Operator: STRACHAN EXPLORATION INC

Inspection Date: 2/21/2024

County: Bent



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing west toward the location. There are tall undesirable weeds at the location that need to be controlled and removed. Previous CA was not completed.



Inspection Photos



Photo 2. Facing toward the meter shed. There is no secondary containment of the fuel/chemical tank behind the shed.



Inspection Photos



Photo 3. There are plastic drums with no labeling and one appears to be empty and not in use.



Inspection Photos



Photo 4. Facing toward the tank battery. There is insufficient secondary containment to contain a spill. Previous corrective action was not completed.



Inspection Photos



Photo 5. The sign at the tank does not reflect the current Operator sand is faded. Previous CA was not completed.



Inspection Photos



Photo 6. Facing northwest at the location.



Inspection Photos



Photo 7. There is a dripping leak at the separator and stained soils. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 8. Facing toward the well. There is an uncapped pipe riser shown at red arrow.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources