

Inspection Photos

API: 099-06063

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 2/21/2024

County: Prowers



Inspection Photos



Photo 1. Facing northeast toward the tank battery. The berm has been built up around the tank and the fence was repaired.



Inspection Photos



Photo 2. Facing northeast toward the wellsite. There still appears to be oil staining that needs to be cleaned up better.



Inspection Photos



Photo 3. Facing toward the tank battery. The berm has been rebuilt and a fence was installed around the tank battery.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API: 099-06063 | Date: 2/21/2024

Inspection Photos



Photo 4. Facing southeast at the location. Unused areas of the location need to be reclaimed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 5. Facing toward the well pumpjack.



Inspection Photos



Photo 6. Facing toward the tank battery. It appears impacted soils have been cleaned up and netting was installed on the open top tank.

