

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 11-8 (I11W) Pad

Location ID: 334561



Feb 21, 2024 at 2:25:23 PM  
CO

**Photo # 7225 From entrance to location**



Feb 21, 2024 at 2:25:10 PM  
CO

**Photo # 7226 From entrance to location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 11-8 (I11W) Pad

Location ID: 334561




Photo # 7227 Location



Photo # 7228 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 11-8 (I11W) Pad

Location ID: 334561



Feb 21, 2024 at 2:27:19 PM  
CO



Feb 21, 2024 at 2:27:54 PM  
CO


Photo # 7229 Location

Photo # 7230 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 11-8 (I11W) Pad

Location ID: 334561



Feb 21, 2024 at 2:29:50 PM  
CO

Photo # 7231 Location



Feb 21, 2024 at 2:31:18 PM  
CO

Photo # 7232 Location



## Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 11-8 (I11W) Pad

Location ID: 334561



**Photo # 7233 Flowline heating insulation open  
ended/wildlife hazard/available for entry by wildlife**