

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 2/22/2024



Wellheads – Photo #09458



Separators – Photo #09463

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 2/22/2024



Tank Battery – Photo #09467



Tank Not Labeled – Photo #09468

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 2/22/2024



Debris – Photo #09462



Unprotected Soil Stockpile – Photo #09460

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 2/22/2024



Unprotected Soil Stockpile – Photo #09461



Insufficient Erosion Control – Photo #09464

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM-66S96W/23SWSW

Location ID: 335388

Date: 2/22/2024



Insufficient Erosion Control/Sediment Encroaching on Production Equipment – Photo #09465



Lack of Stabilization/Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #09466