

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad

Location ID: 311608



Photo # 7377 From entrance to location



Photo # 7378 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad

Location ID: 311608



Feb 22, 2024 at 11:26:48 AM
CO

Photo # 7379 Location



Feb 22, 2024 at 11:40:39 AM
CO

Photo # 7380 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad

Location ID: 311608



Photo # 7381 Location



Photo # 7382 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad

Location ID: 311608



Photo # 7383 Location



Photo # 7384 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad

Location ID: 311608



Photo # 7385 Hole in liner/liner needs maintenance



Photo # 7386 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad

Location ID: 311608



Photo # 7387 Hole in liner/liner needs maintenance



Photo # 7388 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SCHAEFFER 12-6C (F12W) Pad

Location ID: 311608



Photo # 7389 Hole in liner/liner needs maintenance



Photo # 7390 Hole in liner/liner needs maintenance