

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER 12-3 (D12) Pad

Location ID: 334603



Photo # 7343 From entrance to location



Photo # 7344 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER 12-3 (D12) Pad

Location ID: 334603



Photo # 7345 Location



Photo # 7346 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER 12-3 (D12) Pad

Location ID: 334603



Photo # 7347 Hole in liner/liner needs maintenance



Photo # 7348 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER 12-3 (D12) Pad

Location ID: 334603



Photo # 7349 Flowline heating insulation open ended/wildlife hazard/available for entry by wildlife



Photo # 7350 Battery sign laying on the ground/sign not properly posted

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER 12-3 (D12) Pad

Location ID: 334603



Photo # 7351 Sign laying on the ground



Photo # 7352 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER 12-3 (D12) Pad

Location ID: 334603



Photo # 7353 Debris



Photo # 7354 Debris

Inspection Photos

Location Name: CAERUS PICEANCE LLC SHAEFFER 12-3 (D12) Pad

Location ID: 334603



Photo # 7355 Debris