

# Interim Reclamation and Stormwater Inspection

Date: 02/22/2024

Operator: EXTRACTION OIL & GAS INC - 10459

Location ID: 446906

Inspection Document #: 708200940

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Winder South 9-E Pad  
Location ID: 466906



**Photo 1.** Interim reclamation activities have been performed to reduce the size of the pad only needed for production operations.



Inspection Photos  
Location Name: Winder South 9-E Pad  
Location ID: 466906



**Photo 2.** South side of location. Interim areas are currently fallow cropland. A future inspection will be conducted during the next growing season to verify vegetative compliance with Rule 1003.



Inspection Photos  
Location Name: Winder South 9-E Pad  
Location ID: 466906



**Photo 3.** Erosion degradation (e.g. riling) observed on the western side of the location. Stormwater control measure/BMPs should be implemented to prevent sediment laden stormwater from exiting off location and into adjacent cropland.



Inspection Photos  
Location Name: Winder South 9-E Pad  
Location ID: 466906



**Photo 4.** West side of location; see comments in Photo 3.



Inspection Photos  
Location Name: Winder South 9-E Pad  
Location ID: 466906



**Photo 5.** Taken from inside of location, west side. See comments in Photo 3.