

# Interim and Stormwater Inspection

February 12, 2023

Operator: GMT Exploration Company LLC - #10243

Location ID: 479194

Inspection Document #: 709400805

Elbert County, CO

SESE Section 23 T6S R65W

Reed Wold  
Reclamation Specialist, COGCC




**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Irwin Taylor pad  
Facility ID: 479194



**Photo 1.** Photo taken of location sign.



**Photo 2.** Photo taken of wellhead on site. Photo taken facing northeast.



Inspection Photos  
Location Name: Irwin Taylor pad  
Facility ID: 479194



**Photo 3.** Photo taken of tank battery on site. Photo taken facing southeast.



**Photo 4.** Photo taken of vegetation in topsoil stockpile in interim reclaimed area of well pad. Photo taken facing south.



Inspection Photos  
Location Name: Irwin Taylor pad  
Facility ID: 479194



**Photo 5.** Photo taken of vegetation on topsoil stockpile in interim reclaimed area of well pad. Photo taken facing north.



**Photo 6.** Photo taken of vegetation on topsoil stockpile in interim reclaimed area of well pad. Photo taken facing north.



Inspection Photos  
Location Name: Irwin Taylor pad  
Facility ID: 479194



**Photo 7.** Photo of weeds (russian thistle) in perimeter ditch on the east side of site. Photo tank facing north.



**Photo 8.** Photo of weeds (russian thistle & kochia) on the east side of pad. Photo taken facing south.



Inspection Photos  
Location Name: Irwin Taylor pad  
Facility ID: 479194



**Photo 9.** Photo of sediment laden check dams in perimeter ditch . Photo tank facing north.



**Photo 10.** Photo of sediment laden check dams in perimeter ditch . Photo tank facing west.



Inspection Photos  
Location Name: Irwin Taylor pad  
Facility ID: 479194



**Photo 11.** Photo of large sediment basin on north side of pad.  
Photo taken facing west.



**Photo 12.** Photo of reeling in pad perimeter on the west side of pad. Photo taken facing west.