

Operator: Extraction Oil and Gas
Location Name: Winder South 9-E Pad
Loc ID: 446906
Inspection: 708200940



Exhibit A



Exhibit B



Exhibit C

CA: This location does not comply with Rule 1002.f. During this inspection, Staff observed erosion degradation (e.g. riling) occurring on the west side of the production areas. Stormwater control measures/BMPs should be implemented to prevent stormwater runoff, and sediment, from entering adjacent cropland. Refer to attached inspection photos. Install or repair required BMPs per Rule 1002.f.

CA Resolution: BMPs have been repaired to comply with Rule 1002.f.