

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/29/2024

Submitted Date:

02/29/2024

Document Number:

698705903**FIELD INSPECTION FORM**Loc ID 318413 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Silver, Randy		randy.silver@state.co.us	
,		cogcc@kpk.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241253	WELL	SI	11/01/2021	GW	123-09041	UPRR 43 PAN AM I 21	SI

General Comment:[Wellsite Inspection](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	OTHER		
Comment:	Mechanical issue no prime mover on pumpjack		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: <u>03/14/2024</u>
Type	UNUSED EQUIPMENT		
Comment:	Pumpjack has no motor to operate needs to be removed		
Corrective Action:	Comply with rule 606		Date: <u>03/14/2024</u>

Overall Good: ☐

Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electrical panel		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 241253 Type: WELL API Number: 123-09041 Status: SI Insp. Status: SI

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment:

SI
Flowline valve is closed PU has not had a motor since last inspection in 2020 per document #693503984. Operator is showing oil production with PU not being able to operate. Well will sent to engineering for further review.

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday February 29, 2024 at approximately 12:10 pm, I, Inspector Abe Serna, conducted an on-site inspection. Location: UPPR 43 PAN AM 21 Operator: KPK API#:123-09041 County: WELD While there, I observed a SI Well During this inspection the following possible compliance issues were observed: Unused equipment: Rule 606 CA Date 3-14-24 See photos Mechanical issue: Rule 608 CA Date 3-14-24 See photo Contact engineering for review of production records Weather conditions: Sunny A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>Any corrective actions from previous inspections that have not been addressed are still applicable</p>	sernaa	02/29/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698705904	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6448966