

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7570 From entrance to location



Photo # 7571 From entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7572 Location



Photo # 7573 Location



Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7574 Location



Photo # 7575 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Feb 26, 2024 at 11:22:22 AM
CO

Photo # 7576 Location



Feb 26, 2024 at 11:22:47 AM
CO

Photo # 7577 Location



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7578 Location



Photo # 7579 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7580 Location



Photo # 7581 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163




Photo # 7582 PRV vent line lacks cap



Photo # 7583 PRV vent line lacks cap



Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163




Photo # 7584 Hole in liner/liner needs maintenance




Photo # 7585 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7586 Hole in liner/liner needs maintenance



Photo # 7587 Hole in liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7588 Stained soils & gravel



Photo # 7589 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7590 Stained soils & gravel



Photo # 7591 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC GMU 23-14 (C26NW) Pad

Location #: 335163



Photo # 7592 Stained soils & gravel



Photo # 7593 Stained soils & gravel