

WELL NAME: CARIBOU 42-32, API #: 071-08763, INSP. # 695109160



PHOTO 1: WELL SIGN





PHOTO 2: LOCATION





PHOTO 3: WELLHEAD AND EQUIPMENT



PHOTO 4: BMP'S ALONG ROW ARE NOT ADEQUATE OR HAVE FAILED, EROSION AND COMPACTION ISSUES CAUSING HEAVE TRENCHING ON ROW. REPAIR OR INSTALL AND MAINTAIN PROPER EROSION AND MIGRATION BMP'S PER RULE 1002. CA DATE 3-29-2024.





PHOTO 5: BMP'S ALONG ROW ARE NOT ADEQUATE OR HAVE FAILED, EROSION AND COMPACTION ISSUES CAUSING HEAVE TRENCHING ON ROW. REPAIR OR INSTALL AND MAINTAIN PROPER EROSION AND MIGRATION BMP'S PER RULE 1002. CA DATE 3-29-2024.

