

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7827 From entrance to location

Photo # 7828 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7829 Location



Photo # 7830 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Feb 28, 2024 at 2:20:35 PM
CO



Feb 28, 2024 at 2:35:30 PM
CO

Photo # 7831 Location

Photo # 7832 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Feb 28, 2024 at 2:22:04 PM
CO



Feb 28, 2024 at 2:22:39 PM
CO

Photo # 7833 Location

Photo # 7834 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Feb 28, 2024 at 2:30:47 PM
CO



Feb 28, 2024 at 2:31:54 PM
CO

Photo # 7835 Location

Photo # 7836 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7837 Location

Photo # 7838 Location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7839 Hole in containment liner/liner needs maintenance



Photo # 7840 Hole in containment liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7841 Hole in containment liner/liner needs maintenance



Photo # 7842 Hole in containment liner/liner needs maintenance

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7843 Methanol tank lacks required info



Photo # 7844 Methanol tank lacks required info

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7845 Wildlife protection on containment needs maintenance



Photo # 7846 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7847 Stained soils & gravel



Photo # 7848 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7849 Stained soils & gravel



Photo # 7850 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7851 Stained soils & gravel



Photo # 7852 Stained soils & gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7853 Stained gravel



Photo # 7854 Stained gravel

Inspection Photos

Location Name: CAERUS PICEANCE LLC ALP Fee 24-6B (J24NW) Pad

Location #: 335058



Photo # 7855 Stained gravel