

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/21/2024

Submitted Date:

02/23/2024

Document Number:

713600775

## FIELD INSPECTION FORM

Loc ID 314177 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: 

## Operator Information:

OGCC Operator Number: 74165

Name of Operator: RENEGADE OIL &amp; GAS COMPANY LLC

Address: 6155 S MAIN STREET #225

City: AURORA State: CO Zip: 80016

## Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

## Findings:

4 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE

## Contact Information:

Contact Name	Phone	Email	Comment
Ingve, Ed	303-829-2354	ed@renegadeoilandgas.com	

## Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
227737	WELL	PR	12/01/2021	GW	099-06063	IDLER C 1	RI
447057	TANK BATTERY	AC	07/29/2016		-	IDLER C-622S47W 29SWSW	RI

## General Comment:

This is a follow up of the previous reclamation inspection #713600203.  
See attached photos and additional details within this report.

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	The open top tank labeling is inaccurately posted as produced water and there is crude oil in the tank. Previous corrective action was not completed.		
Corrective Action:	Install sign to comply with Rule 605.h. and accurately show contents in the tank.	Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: The stained soils at the tank battery appear to be cleaned up. There is still some residual staining where impacted soils were dumped on the pad. Additional cleanup is needed. (See Photo 2).

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	The fence at the tank battery has been rebuilt.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1		Open Top		,	
Comment:	The netting on the open top tank has been repaired.					
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Inadequate
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403696714	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6440390">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6440390</a>
713600776	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6440387">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6440387</a>