

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/04/2024

Submitted Date:

03/04/2024

Document Number:

698705923

FIELD INSPECTION FORM

Loc ID: 320188 Inspector Name: Serna, Abe On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 6 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	
		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202953	WELL	PR	06/01/2019	OW	001-08358	GUTHRIE 2	PR

General Comment:

Wellsite & Tank Battery Inspection due to Complaint Doc #403703459

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Sign or label not posted or information inaccurate on tanks or containers or sign/label too small to read at distance or installed in place where not visible.		
Corrective Action:	Comply with rule 605.h.	Date:	04/05/2024

Emergency Contact Number:		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil around wellheadUse when oily waste is E&P waste, especially around or in tank berms, load out lines. You can use this rule when you find small localized areas of oil/condensate staining that need to be cleaned up. Can always use in conjunction with 912.a. & b for reportable spills. DO NOT USE FOR REFINED OILS, USED OILS, OR DIESEL FUEL.		
Corrective Action:	905.e.	Date:	04/05/2024
Type	OTHER		
Comment:	2-5 gallon buckets in meter house		
Corrective Action:	Comply with rule 606	Date:	04/05/2024
Type	OTHER		
Comment:	Tracking pad not installed or installed improperly or not adequately maintained to prevent track of material offsite 3 total 2 on development Rd & Highway 168 Rd		
Corrective Action:	Comply with rule 1002.f.	Date:	04/05/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Not calibrated		
Corrective Action:	comply with rule 430.d.(1)	Date:	04/05/2024
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	#		
Comment:	Electrical panel		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER					
Comment:	Sign not posted or information inaccurate at oil and gas location Burried vault with open lid and unknown fluid, no sign or marker				
Corrective Action:	Comply with rule 605.a.				Date: 04/05/2024

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV FIBERGLASS		
Comment:	Shares containment with crude oil tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	300 BBLs	STEEL AST		40.000077,104.862976
-----------	---	----------	-----------	--	----------------------

Comment:					
Corrective Action:					Date:

Paint

Condition	Inadequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Wells Served By Facilities Above

AirsID

API Number	API Number	AirsID
001-08358		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 202953 Type: WELL API Number: 001-08358 Status: PR Insp. Status: PR

Producing Well

Comment:	<u>PR</u>	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test: 09/29/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: _____

End Surf Csg Pressure: --

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Monday March 4, 2024 at approximately 2:00pm, I, Inspector Abe Serna, conducted an on-site inspection. Location: Guthrie #2 Operator: KPK API#:001-28358 County: Weld While there, I observed a Producing well During this inspection the following possible compliance issues were observed: Stained soil: Rule 905.e. CA Date 4-5-24 Tracking Pad: Rule 1002.f. CA Date 4-5-24 Trash Rule 605: CA Date 4-5-24 Signs Tank: Rule 605.H. CA Date 4-5-24 Meter Calibration: Rule 430.d. CA Date 4-5-24 Weather conditions: Sunny A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.</p> <p>Any corrective actions from previous inspections that have not been addressed are still applicable</p>	sernaa	03/04/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698705924	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6453434