

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/26/2024

Submitted Date:

03/05/2024

Document Number:

700901988

FIELD INSPECTION FORM

Loc ID 319728 Inspector Name: Finkenbinder, Chane On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #225
City: AURORA State: CO Zip: 80016

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ingvie, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
, COGCC		conor.pesicka@state.co.us	
Espinosa, Bill		billespinosa30@yahoo.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201151	WELL	SI	04/01/2018	OW	001-06554	UPRR-HABEL 1-35	SI

General Comment:

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	#	Comment	Corrective Action	Date	corrective date
Type: Deadman # & Marked	# 4				
Type: Bird Protectors	# 1				
Type: Bradenhead	# 1				
Type: Horizontal Heated Separator	# 1				
Type: Pump Jack	# 1				

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.837398,-104.296867
Comment:	Rule 905e: Stained soil. Control and contain spills/releases and clean up per Rule 905e.				
Corrective Action:	Corrective Action Date 3/22/2024 to remove stained soil. See attached photo #3				Date: 03/22/2024

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate	
Comment:	Rule 603.o.(1): Maintained berms around tank(s). Corrective Action Date 4/5/2024. See attached photo #2				
Corrective Action:	Corrective Action Date 4/5/2024. See attached photo #2				Date: 04/05/2024
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		
Comment:					
Corrective Action:					Date:
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Insufficient	Inadequate	
Comment:	Rule 603.o.(1): Maintained berms around tank(s).				
Corrective Action:	Corrective Action Date 4/5/2024. See attached photo #2				Date: 04/05/2024
Wells Served By Facilities Above			AirsID		
API Number		API Number		AirsID	
001-06554					
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 201151 Type: WELL API Number: 001-06554 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>CECMC Inspection Report Summary On Monday February 26th, 2024 at approximately 11:52am. I, Inspector Chane Finkenbinder, conducted an on-site follow-up inspection of doc #700901847. Operator: RENEGADE OIL & GAS Location name: UPRR HABEL 1-35 API # 001-06554 Location ID #: 319728 County: Adams While there, I observed a shut in well. During this inspection the following possible compliance issues were observed: Rule 905e: Stained soil. Control and contain spills/releases and clean up per Rule 905e. Corrective Action Date 3/22/2024 to remove stained soil. See attached photo #3 Rule 603.o.(1): Maintained berms around tank(s). Corrective Action Date 45/5/2024. See attached photo #2 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	03/05/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700901989	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6454380