

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 8193 From entrance to location



Photo # 8194 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510




Photo # 8195 Location



Photo # 8196 Location



## Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Mar 5, 2024 at 9:24:56 AM  
CO

Photo # 8197 Location



Mar 5, 2024 at 9:26:10 AM  
CO

Photo # 8198 Tank label losing adhesion & some required info is not visible



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 2673 From inspection 708902787 conducted on 01/11/2024 PRV & rupture disc vent lines lack caps



Photo # 8199 PRV & rupture disc vent lines lack caps

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



Photo # 2674 From inspection 708902787 conducted on 01/11/2024 PRV & rupture disc vent lines lack caps



Photo # 8200 PRV & rupture disc vent lines lack caps

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC MOBILE 11-20 Pad

Location #: 322510



**Photo # 8201 Barbed wire fence needs maintenance/barbed wire laying on ground/wildlife hazard**