

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/25/2024

Submitted Date:

02/28/2024

Document Number:

698601562**FIELD INSPECTION FORM**Loc ID 303574 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10536Name of Operator: SMITH ENERGY LLCAddress: 1540 MAIN ST SUITE 218 #334City: WINDSOR State: CO Zip: 80550**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**17 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Glenn	970-381-6253	smithenergy@live.com	
Smith, Chris	970-330-7034	smithenergy@live.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253311	WELL	PR	04/01/2017	GW	125-07188	CROSSLAND 1-2	PR

General Comment:

Routine Inspection.

Location

Lease Road:			
Type	Access		
comment:	Two track off maintained County Road. Active agricultural cropland with seasonal access to well location.		
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign located at wellhead.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well sign posted at gas meter run.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Content/Quantity/Hazard sign at tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Emergency contact information posted on well sign, gas meter run sign, and tank sign.

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel post and tube panels.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 0		
Comment:	Bradenhead is not plumbed to surface. Bradenhead inaccessible and not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1). (2)	Date:	03/11/2024
Type: Gas Meter Run	# 1		
Comment:	Remote Gas Meter Run located on CR 54. Gas Meter Run. Chart in Meter Box dated 12-29-23. Meter Calibration/Test Log dated 9-15-23. Well Inlet Valve open. Gas Outlet Valve open.		
Corrective Action:		Date:	
Type: Dehydrator	# 1		

Comment:	Dehydrator on gas meter run inlet.		Date:	
Corrective Action:			Date:	
Type: Vertical Separator	# 1			
Comment:			Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Separator Shed at remote Gas Meter Run.		Date:	
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Meter Shed at remote Gas Meter Run.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Wellhead. Rods removed from wellbore. Tubing valve open. Casing valve not connected.		Date:	
Corrective Action:			Date:	
Type: Pump Jack	# 0			
Comment:	Removed.		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV PLASTIC		,
Comment:	Located at remote gas meter run on CR 54. Tank hatch is missing plug and open to atmosphere.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	24 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities									
Facility ID:	253311	Type:	WELL	API Number:	125-07188	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Rods removed from wellbore. Tubing valve open. Casing valve not connected. Gas Meter Run Valves: Well inlet valve open, Gas outlet valve open. Electronic Well File reflects last Production/Status reported 12/1/2023 and Well Status as PR. Based on current valve settings at time of inspection the well is PR.								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No stormwater issues noted at time of inspection.

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403701866	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6446609
698601666	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6446601