

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/06/2024

Submitted Date:

03/06/2024

Document Number:

715400058

FIELD INSPECTION FORMLoc ID 327420 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| , Oxy | | ECMCInspections@Oxy.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 427328 | WELL | PR | 08/01/2019 | OW | 123-34947 | CAMP 15N-26HZ | PR |

General Comment:

Corrective action inspection. Weed debris at wellhead.

LocationOverall Good: ☒

| | | | |
|----------------------|----------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | |
|---------------------------|--------------------------|------------------|
| Good Housekeeping: | | |
| Type | WEEDS | |
| Comment: | Weed debris at wellhead. | |
| Corrective Action: | Comply with Rule 606 | Date: 03/14/2024 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | |
|--------------------|------------|-------|
| Fencing/: | | |
| Type | WELLHEAD | |
| Comment: | Pipe panel | |
| Corrective Action: | | Date: |

| | | | |
|--------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Plunger Lift | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---------------------------------|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | Battery location number: 427327 | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
|------|----------|---------------------|---------------------|-------------|

| | | | | | |
|--------------------|--|--|--|--|-------|
| | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | | | | | | | |
|---|----------------------------|---|------------------------|-------------|------------|---------|----|---------------|----|
| Inspected Facilities | | | | | | | | | |
| Facility ID: | 427328 | Type: | WELL | API Number: | 123-34947 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| BradenHead | | | | | | | | | |
| Date of Last Brhd Test: | 09/27/2023 | | Annual Brhd Completed? | Yes | | | | | |
| Last Brhd Test Results | Initial Surf Csg Pressure: | 20 | Fluid Type: | WATER H20 | | | | | |
| | End Surf Csg Pressure: | 0 | | | | | | | |
| Comment: | Plumbed to surface. | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |
| COGCC Comments | | | | | | | | | |
| Comment | | | | User | Date | | | | |
| Corrective action inspection. Weed debris at wellhead. | | | | carlilec | 03/06/2024 | | | | |
| Attached Documents | | | | | | | | | |
| You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number: | | | | | | | | | |
| Document Num | Description | URL | | | | | | | |
| 715400059 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6455543 | | | | | | | |