

Inspection Photos
Location Name: Darlene East 29-N-20-11C
Location ID: 452153



Photo 1 – Pumping Unit

Photo 2 – Wellhead

Inspection Photos
Location Name: Darlene East 29-N-20-11C
Location ID: 452153



Energy and Carbon Management Commission
40-9741, -104-22678, 5199.4ft
03/05/2024 12:46:56



Energy and Carbon Management Commission
40-9744, -104-2276, 5195.4ft
03/05/2024 12:47:19

Photo 3 – Well Sign

Photo 4 – Maintenance Tank

Inspection Photos
Location Name: Darlene East 29-N-20-11C
Location ID: 452153



Photo 5 – Tank Battery

Photo 6 – NFPA Label missing on Produced Water Tank

Inspection Photos
Location Name: Darlene East 29-N-20-11C
Location ID: 452153



Photo 7 – Tank Battery Sign

Photo 8 – Lid Cover is open to Atmosphere

Inspection Photos
Location Name: Darlene East 29-N-20-11C
Location ID: 452153



Photo 9 – ECDs

Photo 10 – Separators

Inspection Photos
Location Name: Darlene East 29-N-20-11C
Location ID: 452153



Energy and Carbon Management Commission
40.97452, -104.22667, 5206.7ft
03/05/2024 12:49:06



Energy and Carbon Management Commission
40.97444, -104.2264, 5206.2ft
03/05/2024 12:49:15

Photo 11 – Separator

Photo 12 – Flare

Inspection Photos
Location Name: Darlene East 29-N-20-11C
Location ID: 452153



Photo 13 – Gas Meter Houses