

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2024

Submitted Date:

03/08/2024

Document Number:

698706000

FIELD INSPECTION FORM

Loc ID 328203 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
/, Chevron		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections
,		randy.silver@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247895	WELL	TA	12/01/2019	GW	123-15693	GUNTHER B18-1	TA

General Comment:[Wellsite Inspection](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type

DEBRIS

Comment: Debris in wellhead area need to be removed & hauled off

Corrective Action: Statewide unnecessary equipment, weeds, waste, and trash requirements
Comply with Rule 606

Date: 03/22/2024

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Panels

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 247895 Type: WELL API Number: 123-15693 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TA
6A on file
Master valve is closed & LOTO

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 04/05/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On 3/8/24 at approximately 7:45 am, I, Inspector Abe Serna, conducted an on-site inspection. Location: Gunther B 18-1 Operator: Noble Energy API#: 123-15693 County: Weld While there, I observed a TA Well During this inspection the following possible compliance issues were observed: Debris inside wellhead area Action Date) See attached photo #. 2 Weather conditions: Overcast A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report. Any corrective actions from previous inspections that have not been addressed are still applicable	sernaa	03/08/2024

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698706001	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458485