

Inspection Photos

3/06/2024

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916

Inspection Doc: 696205659

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 1: Photos taken from the working pad surface of the Location. Photo shows BMPs to stabilize the working pad surface, as well as to minimize tracking and sediment transport have not been maintained in a proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 2: Photos taken from the working pad surface of the Location. Photo shows BMPs to stabilize the working pad surface, as well as to minimize tracking and sediment transport have not been maintained in a proper functioning condition.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 3: Photos taken from an outlet on the southeast end of the Location. Outlet has not been installed or maintained in proper functioning condition per good engineering practice; erosion degradation evident to the slopes and the control measure.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 4: Photo left example of erosion degradation observed along the eastern areas of the Location. Photo right example showing sediment deposition within the interim areas of the Location due to stormwater runoff from the pad. Sediment appears to be impacting vegetation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 5: Photo taken from the access road north of the Location. Photos examples showing the access road lacks stabilization and appropriate BMPs to manage runoff.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 6: Photos 6-10 taken from the access road north of the Location. Photos examples showing that the road has not been constructed with a properly engineered stream crossing; vehicle tracking and degradation apparent at the crossing, impacting a riverine system and Waters of the State. Stream is a direct tributary to the Colorado river.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 7: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 8: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 9: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location ID: 323916



Photo 10: See comments under photo 6.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources