

Final Reclamation Inspection

March 6th, 2024

Operator: Hilcorp Energy Company - 10133

Location ID: 325510

Inspection Document #: 714000521

La Plata County, CO

Township: NENW 4 33N 10W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



Photo 1. Overview of the disturbance taken from the entrance facing center.

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of stormwater BMPs that are inadequate and have not been installed per good engineering practices.

API #: 067-06524

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



Photo 3. View of additional stormwater BMPs in the eastern interim reclamation area that are inadequate and have not been installed per good engineering practices. Rill and gully erosion forming down hill of the BMPs.

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510




Photo 4. View of unused oil and gas equipment on location.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06524

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. View of rutting observed site wide; additional stabilization is needed to minimize site degradation.

API #: 067-06524

Inspection Photos
Location Name: Davis Gas Unit 1
Location ID: 325510



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of reference area comprised of smooth brome, crested wheatgrass, sagebrush and juniper.

API #: 067-06524