

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/08/2024

Submitted Date:

03/08/2024

Document Number:

698706000

## FIELD INSPECTION FORM

Loc ID 328203 Inspector Name: Serna, Abe On-Site Inspection ☐ 2A Doc Num: **Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		randy.silver@state.co.us	
/, Chevron		rbucogccinspectionreports@c hevron.onmicrosoft.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
247895	WELL	TA	12/01/2019	GW	123-15693	GUNTHER B18-1	TA

**General Comment:**[Wellsite Inspection](#)

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

DEBRIS

Comment: Debris in wellhead area need to be removed &amp; hauled off

Corrective Action: Statewide unnecessary equipment, weeds, waste, and trash requirements  
Comply with Rule 606

Date: 03/22/2024

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Panels

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Bradenhead

# 1

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 247895 Type: WELL API Number: 123-15693 Status: TA Insp. Status: TA

**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA  
6A on file  
Master valve is closed & LOTO

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/05/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 4 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
ECMC Inspection Report Summary On 3/8/24 at approximately 7:45 am, I, Inspector Abe Serna, conducted an on-site inspection. Location: Gunther B 18-1 Operator: Noble Energy API#: 123-15693 County: Weld While there, I observed a TA Well During this inspection the following possible compliance issues were observed: Debris inside wellhead area Action Date) See attached photo #. 2 Weather conditions: Overcast A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.  Any corrective actions from previous inspections that have not been addressed are still applicable	sernaa	03/08/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403712794	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458489">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458489</a>
698706001	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458485">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6458485</a>