

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9764 From entrance to location




Photo # 9765 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9766 Location



Photo # 9767 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9768 Location



Photo # 9769 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9770 Location



Photo # 9771 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9772 PRV vent line does not comply with CECMC pressure safety device rules & also terminates in an unsafe manner.



Photo # 9773 Cellar lacks wildlife egress/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9774 Cellar cover not properly installed/wildlife & personnel hazard



Photo # 9775 Cellar cover not properly installed/wildlife & personnel hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9776 Cellular cover not properly installed/wildlife & personnel hazard



Photo # 9777 Cellular lacks wildlife egress/wildlife hazard

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC Valley Farms I Pad

Location ID: 335553



Photo # 9778 Cellar lacks wildlife egress/wildlife hazard