

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRIPORT 14-22 Pad

Location ID: 322506



Photo # 9141 From entrance to location



Photo # 9142 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRIPORT 14-22 Pad

Location ID: 322506



Photo # 9143 Location



Photo # 9144 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRIPORT 14-22 Pad

Location ID: 322506



Photo # 9145 Location



Photo # 9146 Tank label damaged & some required information is illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FRIPORT 14-22 Pad

Location ID: 322506




Photo # 9147 PRV & rupture disc vent lines lack caps/do not comply with CECMC pressure safety device rules



Photo # 9148 PRV & rupture disc vent lines lack caps/do not comply with CECMC pressure safety device rules