

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



Photo # 2 From entrance to location



Photo # 3 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



Photo # 4 Location



Photo # 5 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246




Photo # 6 Location



Photo # 7 Unused equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246




Photo # 8 PRV & rupture disc vent lines lack caps/do not comply with CECMC pressure safety device rules




Photo # 9 PRV & rupture disc vent lines lack caps/do not comply with CECMC pressure safety device rules

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC LAST DANCE 10-3 Pad

Location ID: 324246



Photo # 10 Debris