

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413



Photo 1 – Wellhead

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413



Photo 3 – Compressor, Gas Meters and VRU

Photo 4 – Separators

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413



Photo 5 – Tank Battery




Photo 6 – Tank Battery Sign

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413



Photo 7 – ECD



Photo 8 – Compressor

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413



Energy and Carbon Management Commission
40.71612, -103.95503, 4790.7ft
03/19/2024 12:36:27



Energy and Carbon Management Commission
40.71615, -103.95497, 4763.9ft
03/19/2024 12:36:41

Photo 9 – Stained Soil

Photo 10 – Oily Waste

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413





Photo 10 – Stained Soil and Oily Waste

Photo 12 – Stained Soil

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413



Energy and Carbon Management Commission
40.71611, -103.95499, 4755.8ft
03/19/2024 12:37:36

Photo 13 – Oily Waste



Energy and Carbon Management Commission
40.7161, -103.95503, 4751.5ft
03/19/2024 12:37:44

Photo 14 – Stained Soil

Inspection Photos
Location Name: Castor LC 27-72HN
Location ID: 422413



Energy and Carbon Management Commission
40.71617, -103.95512, 4761.8ft
03/19/2024 12:37:56

Photo 15 – Wildlife Netting in disrepair



Energy and Carbon Management Commission
40.7161, -103.95511, 4764.1ft
03/19/2024 12:38:04

Photo 16 – Wildlife Netting in disrepair