

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Stormwater BMPs need implementation



As signs are replaced additional information is required

KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154



Ant Hill Unit not WRD Federal



Ant Hill Unit not WRD Federal

KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154



Debris



Oily waste placed on containment

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Oily waste and staining




Impervious berm?

KT Resources LLC
 Ant Hill Unit 30-42
 Location ID: 316154



Replace labels as needed



Out of date calibration

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Erosion and sediment migration



Oily waste blown out of separator

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Oily waste and stained soil



Rain protection missing on relief riser

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Location from Southeast corner



Location from Northeast corner

**KT Resources LLC
Ant Hill Unit 30-42
Location ID: 316154**



Location from Northwest corner

Location from Southwest corner