

**KT Resources LLC
Federal A 5
Location ID: 314930**



Erosion and sediment migration



Erosion and sediment migration

**KT Resources LLC
Federal A 5
Location ID: 314930**



Sediment migration



Oily waste and stained soil

**KT Resources LLC
Federal A 5
Location ID: 314930**



Display. No gas calibration card



Oily waste and stained soil

**KT Resources LLC
Federal A 5
Location ID: 314930**



Debris. Cap for separator reservoir



Open to wildlife. Cap on the ground.

**KT Resources LLC
Federal A 5
Location ID: 314930**



Oily waste and stained soil



Oily waste and stained soil

**KT Resources LLC
Federal A 5
Location ID: 314930**



Oily waste and stained soil



Debris

KT Resources LLC
Federal A 5
Location ID: 314930



Debris



As signs are replaced additional information is required

**KT Resources LLC
Federal A 5
Location ID: 314930**



Unsafe cellar covering



Unsafe cellar covering

**KT Resources LLC
Federal A 5
Location ID: 314930**



Debris



Erosion and sediment migration

**KT Resources LLC
Federal A 5
Location ID: 314930**



Sediment migration



Last year's weeds

**KT Resources LLC
Federal A 5
Location ID: 314930**



Location from Northeast corner

Location from Northwest corner

**KT Resources LLC
Federal A 5
Location ID: 314930**



Location from Northeast corner

Location from Southeast corner