

Inspection Photos
Location Name: Grant 4
Location ID: 311319



Photo 1 Location.



Photo 2 Dead vegetation(debris) just outside of wellsite fencing.

Inspection Photos
Location Name: Grant 4
Location ID: 311319



Photo 5 Dead vegetation(debris) between the wellsite fencing & pump jack fencing.



Photo 6 Electric panel, pump jack.

Inspection Photos
Location Name: Grant 4
Location ID: 311319



Photo 7 Ancillary equip.