

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2024

Submitted Date:

03/21/2024

Document Number:

702403221

**FIELD INSPECTION FORM**Loc ID 318225 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	<a href="#">All Inspections</a>
,		cogcc@kpk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240919	WELL	SI	06/01/2021	GW	123-08707	GUADAGNOLI 2	SI

**General Comment:**[This is a wellsite inspection](#)

**Location**Overall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate the sign is fading and will need to be replaced in the future.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date:	
Corrective Action:		Date:	

**Good Housekeeping:**

Type	DEBRIS		
Comment:	dead weeds & trash (debris) along access road & throughout location inside fencing and outside of fencing.		
Corrective Action:	Comply with Rule 606	Date:	03/29/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	chainlink topped with barb wire		
Corrective Action:		Date:	

**Equipment:**

Type: Prime Mover	# 1		corrective date
Comment:	electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	electric panels & meter box		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities										
Facility ID:	240919	Type:	WELL	API Number:	123-08707	Status:	SI	Insp. Status:	SI	
Idle Well										
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder:				
Comment:		SI since 5-2021 & last produced 4/2021. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.								
Corrective Action:		Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.					Date:			04/21/2024
BradenHead										
Date of Last Brhd Test:		08/25/2023		Annual Brhd Completed?		Yes				
Last Brhd Test Results		Initial Surf Csg Pressure:		0		Fluid Type:				
		End Surf Csg Pressure:		0						
Comment:		plumbed to surface								
Corrective Action:							Date:			

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment: <input type="text"/>						Date: <input type="text"/>
Corrective Action: <input type="text"/>						
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

COGCC Comments

Comment	User	Date
ECMC Inspection Report Summary On Thursday 2-21-2024 at approximately 1530 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: This Field Inspection is due to a 901 order. Operator: KP Kauffman Location name: Location ID # 318225 Well Name: Guadagnoli 2 API # 05-123-08707 County: Weld Weather: Sunny/Clear Location: Mostly dry. While there, I observed a wellsite, SI at the time of the inspection. During this inspection, I observed the following possible compliance issues: 606 housekeeping: Debris, CA date 3-29-2024. 417.b MIT: Shut in wells, CA date 4-21-2024. See attached photos. A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules. Any Corrective Actions from previous inspections not addressed are still applicable	revasr	03/21/2024

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702403222	location photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477211">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477211</a>