

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL SAVAGE 11-4A (RD11) Pad

Location # 335004



Photo # 854 From entrance to location




Photo # 855 Location

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL SAVAGE 11-4A (RD11) Pad

Location # 335004



Photo # 856 Location



Photo # 857 Location



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC FEDERAL SAVAGE 11-4A (RD11) Pad**  
**Location # 335004**



**Photo # 858 Location**



**Photo # 859 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL SAVAGE 11-4A (RD11) Pad

Location # 335004



Photo # 860 Location



Photo # 861 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL SAVAGE 11-4A (RD11) Pad

Location # 335004



Photo # 862 Location



Photo # 863 Location





## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL SAVAGE 11-4A (RD11) Pad

Location # 335004



**Photo # 864 Mechanical condition – fluid leaking from tank valve**



**Photo # 865 Mechanical condition – fluid leaking from tank valve**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC FEDERAL SAVAGE 11-4A (RD11) Pad

Location # 335004



Photo # 866 Open ended load line