

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/13/2024

Submitted Date:

03/17/2024

Document Number:

708903284

**FIELD INSPECTION FORM**

Loc ID 335082	Inspector Name: Smelser, Wayne	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
<b>Operator Information:</b> OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: 1058 COUNTY ROAD 215 City: PARACHUTE State: CO Zip: 81635				<b>Findings:</b> 35 Number of Comments 3 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				<b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>

<b>Contact Information:</b>			
Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	

<b>Inspected Facilities:</b>							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282960	WELL	PR	06/01/2021	GW	045-11888	MCLAUGHLIN 32C-27-692	PR
282962	WELL	PR	03/29/2008	GW	045-11887	MCLAUGHLIN 32B-27-692	PR
282963	WELL	PR	03/30/2008	GW	045-11886	MCLAUGHLIN 42B-27-692	PR
282964	WELL	PR	03/23/2008	GW	045-11885	MCLAUGHLIN 42C-27-692	PR
292117	WELL	PR	03/25/2008	GW	045-14597	MCLAUGHLIN 32D-27-692	PR
292118	WELL	PR	03/21/2008	GW	045-14596	MCLAUGHLIN 32A-27-692	PR
292120	WELL	PR	03/16/2008	GW	045-14595	MCLAUGHLIN 42A-27-692	PR

**General Comment:**

CECMC Inspection Report Summary  
 On 03/13/2024 at approximately 10:12 hours, I, Compliance Specialist, Wayne Smelser  
 Conducted an on-site inspection at TEP ROCKY MOUNTAIN LLC MCLAUGHLIN 42A-27 Pad.  
 Location # 335082 in Garfield County Colorado.  
 Location is within High Priority/Density/Black Bear Habitat areas.  
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Signs/Marker - 42A-27 wellhead sign faded & illegible with a CA date of 04/16/2024
2. Housekeeping - Unused equipment on location with a CA date of 04/16/2024
3. Equipment - Multiple PRV vent lines do not comply with CECMC pressure safety device rules & general safety rules with a CA date of 03/24/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
 This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	42A-27 wellhead sign faded & illegible 2-3 other wellhead signs are also faded & barely legible at this time		
Corrective Action:	Comply with CECMC signage rules	Date:	04/16/2024
Type	OTHER		
Comment:	Sign at intersection of Dry Hollow road & Alta Mesa Road		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911/970-285-9377		
Corrective Action:			Date: _____

<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Small amount of staining near wellhead		
Corrective Action:		Date:	
Type	WEEDS		
Comment:	Small amount of weeds in secondary containment		
Corrective Action:		Date:	
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location - ECD is disconnected & not in use		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.	Date:	04/16/2024

Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Cattle panels			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Cattle panels			
Corrective Action:				Date:
<b>Equipment:</b>				corrective date
Type: Gas Meter Run	# 8			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:	ECD disconnected & not in use, please refer to Housekeeping for CA			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 8			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 7			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Bird Protectors	# 9			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 7			
Comment:	Taylor plugs located on all bradenhead. All bradenhead valves are accessible.			
Corrective Action:				Date:
Type: Other	# 3			
Comment:	PRV vent lines on tank burners terminate in an unsafe manner/do not comply with CECMC pressure safety device rules & general safety rules.			
Corrective Action:	Comply with CECMC pressure safety device rules & general safety rules.			Date: 03/24/2024
Type: Ancillary equipment	# 1			
Comment:	Chemical tank			
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	HEATED STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	375 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	STEEL AST		,
Comment: Tank equipped with telemetry					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	375 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient		
Comment: Centralized containment				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	OTHER	HEATED STEEL AST		,
Comment: Tanks equipped with telemetry					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	375 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Metal	Adequate	Walls Sufficent			
Comment:	Centralized containment				
Corrective Action:					Date:
<b><u>Venting:</u></b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b><u>Flaring:</u></b>					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities				
Facility ID:	282960	Type:	WELL	API Number: 045-11888 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID:	282962	Type:	WELL	API Number: 045-11887 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID:	282963	Type:	WELL	API Number: 045-11886 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID:	282964	Type:	WELL	API Number: 045-11885 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID:	292117	Type:	WELL	API Number: 045-14597 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID:	292118	Type:	WELL	API Number: 045-14596 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		
Facility ID:	292120	Type:	WELL	API Number: 045-14595 Status: PR Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing, well on plunger lift			
Corrective Action:		Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Blankets						
Culverts						
		Ditches				
				Material Handling And Spill Prevention		Chemical tank containment
Compaction						Light compaction in areas
Ditches						
Berms						
Rip Rap						
		Gravel				Sparse to none
		Compaction				
Gravel						Sparse to none in most areas
		Rip Rap				
		Culverts				

Comment: [Some fluid in chemical tank containment, may need maintenance in the near future.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Please refer to Signs/Marker, Housekeeping &amp; Equipment for observed compliance issues.</a>	smelserw	03/17/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403722204	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470326">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470326</a>
708903285	Inspection 708903284 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470324">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470324</a>
708903286	Inspection 708903284 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470325">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6470325</a>